



Ozone

Suspended Particles

Temperature & Relative Humidity

CO₂

Formaldehyde

VOCs

Asbestos

Fungal and Bacteria

Asbestos Analysis
Mahaphant Fibre Cement Public Co., Ltd.
Pattananikhom, Lopburi
January 22, 2009

SGS

Report No. : 2009-00044 / 001 (Page 1 of 1)

Issued date: February 6, 2009

CLIENT : MAHAPHANT FIBRE-CEMENT PUBLIC CO., LTD.
CONTACT : Khun Watcharin
ADDRESS : 59 moo 12, Saraburi-Lomsak Rd., km.16, Tambol Chongsarika,
Amphur Pattananikhom, Lopburi 15220
Tel. 036-638-888 ext.261 Fax: 036-638-638

Analysis Report

SAMPLE DESIGNATED AS : Asbestos Analysis
SAMPLING LOCATION : Fibre Cement Board

SAMPLING TIME : January 22, 2009

Sampling Location	Samples Description	Results
Fibre Cement Board	Shera Flexy Board	N.D.

Remark : - N.D. = No Asbestos Detected
Analysis Method : - Polarised Light Microscopy (PLM) Referring to NIOSH 9002 standard, including Dispersion Staining as per AN-602 Accreditation does not cover the identification of Synthetic Mineral Fibre (SMF).

Siriporn I.

(Siriporn Imwilaiwan)
License ID: ๑-010-๓-1793

(Sompong Kiatiporn)
Environmental Manager

SGS (THAILAND) LIMITED



SKWH/Pp

This report is issued in accordance to the disclaimer statements.